

New York State Commission on the Restoration of the Capitol Photographs of Phases of the Capitol Restoration B2896

New York State Archives 222 Madison Avenue Albany, NY 12230 archref@nysed.gov URL: http://www.archives.nysed.gov/

Table of Contents

Overview of the Records	3
Arrangement	3
Scope and Contents	3
Related Information	4
Use of Records	4
Access Terms	4

Overview of the Records

Repository:	New York State Archives
Summary:	This series consists of photographs documenting the four phases of construction during the Capitol Restoration from 2000-2014. Most of the photographs document the restoration of the Great Western Staircase, the roof and skylight, and later, the Eastern Approach to the Capitol.
Creator:	New York State Commission on the Restoration of the Capitol
Title:	Photographs of phases of the Capitol restoration
Quantity:	5 cubic feet
Quantity:	3120 photographic print(s)
Inclusive Date:	2000-2014
Series:	B2896

A Return to Table of Contents

Arrangement

Chronological.

^ Return to Table of Contents

Scope and Content Note

This series consists of photographs documenting the four phases of construction during the Capitol Restoration from 2000-2014. Most of the photographs document the restoration of the Great Western Staircase, the roof and skylight, and later, the Eastern Approach to the Capitol.

^ Return to Table of Contents

New York State Commission on the Restoration of the Capitol Photographs of Phases of the Capitol Restoration B2896

Related Information

Related Material

B2585 State Commission on the Restoration of the Capitol Chairman's Subject and Correspondence Files

B2595 State Commission on the Restoration of the Capitol Executive Director's Subject and Correspondence Files

B1864 State Commission on the Restoration of the Capitol Restoration Feasibility Studies and Reports

^ Return to Table of Contents

Use of Records

Access Restrictions

There are no restrictions regarding access to or use of this material.

Access Terms

- Photographs
- Historic preservation
- Public buildings
- New York (State)
- Historic buildings--Conservation and restoration
- New York (State). Temporary State Commission on the Restoration of the Capitol
- New York State Capitol (Albany, N.Y.)